


T. 138 R. 32 M. 5TH Coordinates: X _____ Y _____
NE 13 Corner common to sections 12, 13 AND 7, 18-132-31



EXISTING SURVEYS

Original Government Survey

Year surveyed 1860
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Species	Bearing	Trees	
<u>PINE</u>	<u>PINE</u>	<u>W. BIRCH</u>	<u>PINE</u>
Diameter <u>18"</u>	<u>18"</u>	<u>4"</u>	<u>18"</u>
Bearing <u>N 70 W</u>	<u>S 45 E</u>	<u>N 60 E</u>	<u>S 58 W</u>
Distance <u>10 LKS.</u>	<u>12 LKS</u>	<u>30 LKS</u>	<u>60 LKS.</u>

Original Bearing Trees Found

Species	_____
Diameter	_____
Bearing	_____
Distance	_____

○ = Corner

Subsequent Corner Restoration

Year surveyed 1921 By BEN CLARK
 Location filed COUNTY RESURVEY 'E-48"
 Monument IRON MONUMENT
1917- E. B. HORST, COUNTY BOOK 'C' P 63 SET I.M. ←
2x48"
1921, Ben Clark, Book 'C' P 422 FND I.P. ←

Evidence of Subsequent Corner Restoration

Year of search _____ By _____
1917- also on microfilm - roll 115 BK 76 P. 40
1921 also on microfilm - roll 105 BK 53 P. 77

Bearing Trees, Reference Objects

Species	Bearing	Reference Objects
<u>W. PINE STUMP</u>	<u>J. PINE</u>	<u>N. PINE STUMP</u>
Diameter <u>20"</u>	<u>7"</u>	<u>18"</u>
Bearing <u>N 36-20 W</u>	<u>S 29-50 W</u>	<u>S 56-40 E</u>
Distance <u>67.8'</u>	<u>100.5'</u>	<u>35.0'</u>

Bearing Trees, Reference Objects

Species	_____
Diameter	_____
Bearing	_____
Distance	_____

J-25

Subsequent Corner Restoration

Year surveyed 6/05 By CCSO
 Location filed #2004.083
 Monument Found 2" ODIP, down 1.01,
on E Co. Rd. #112 and fence
line East.

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

P. Pole N 24° E, 123.46' *
P. Pole S 11° E, 181.52' *
12" R. Oak N 85° W, 60.41' *
* distance to double head nail