


Index No. N 19

CASS COUNTY LAND CORNER RECORD

T. 138 R. 32 M. 5TH Coordinates: X _____ Y _____
N 14 23 Corner common to sections 14, 23



EXISTING SURVEYS

Original Government Survey
 Year surveyed 1870
 Original monument Post

Species	Bearing	Trees
<u>Bl. Pine</u>	<u>Bl. Pine</u>	
Diameter <u>10"</u>	<u>11"</u>	
Bearing <u>S72W</u>	<u>N79W</u>	
Distance <u>18 LKS</u>	<u>27 LKS</u>	

Original Evidence Found
 Year of search _____ By _____
 Monument found _____

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 12/04 By CCSU
 Location filed # 2004.083
 Monument Found 70" ODIP, RLS #11865, down 0.1', on E 12th St.

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
<u>Fence</u>	<u>Post</u>	<u>North</u>	<u>27.56*</u>
<u>J. Pine</u>	<u>6"</u>	<u>N61°E</u>	<u>57.20*</u>
<u>Fence</u>	<u>Post</u>	<u>S62°W</u>	<u>57.68*</u>

**distance to double head nail*

Evidence of Subsequent Corner Restoration
 Year of search _____ By _____

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
 Location filed _____
 Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search Oct. 2002 By J. Nielsen
Cert of Svy. shows mon found

Remonumentation certificate prepared _____ By _____
 Filed at _____ Date _____