


Index No. N 23

CASS COUNTY LAND CORNER RECORD

T. 138 R. 32 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
N/4 24 Corner common to sections 13, 24



EXISTING SURVEYS

**Original Government Survey**

Year surveyed 1870  
Original monument Post

**Bearing Trees**

Species	<u>N. Pine</u>	<u>Bl. Pine</u>	_____
Diameter	<u>8"</u>	<u>6"</u>	_____
Bearing	<u>S38W</u>	<u>N61/2W</u>	_____
Distance	<u>15 LKS</u>	<u>4 LKS</u>	_____

**Original Evidence Found**

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

**Original Bearing Trees Found**

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

**Subsequent Corner Restoration**

Year surveyed 7/05 By CCSO  
Location filed #2004.083  
Monument Set 1/4" ODIP, down 0.3',  
6'± S. of & 12th St.

**Evidence of Subsequent Corner Restoration**

Year of search \_\_\_\_\_ By \_\_\_\_\_

**Bearing Trees, Reference Objects**

Species	<u>J. Pine</u>	<u>Aspen</u>	<u>J. Pine</u>
Diameter	<u>6"</u>	<u>6"</u>	<u>6"</u>
Bearing	<u>N19°W</u>	<u>S21°E</u>	<u>S42°W</u>
Distance	<u>43.54'*</u>	<u>38.88'*</u>	<u>40.15'*</u>

\*distance to double head nail

**Bearing Trees, Reference Objects**

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

**Subsequent Corner Restoration**

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

**Evidence of Subsequent Corner Restoration Found**

Year of search \_\_\_\_\_ By \_\_\_\_\_