


Index No. V13

CASS COUNTY LAND CORNER RECORD

T. 138 R. 32 M. 5th Coordinates: X _____ Y _____
NE 33 Corner common to sections 27, 28, 33, 34



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1870
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species	<u>N. Pine</u>	<u>N. Pine</u>	<u>N. Pine</u>	<u>N. Pine</u>
Diameter	<u>11"</u>	<u>10"</u>	<u>7"</u>	<u>8"</u>
Bearing	<u>S37E</u>	<u>N26 1/2 E</u>	<u>N41W</u>	<u>S15W</u>
Distance	<u>23 LKS</u>	<u>34 LKS</u>	<u>50 LKS</u>	<u>60 LKS</u>

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 3/2001 By CCSO
Location filed file # 2001.019
Monument Found 1 1/2" OD IP, down 0.7' 4' ±
N. of E 20th St and 4' ± W. of E 22nd St.
1 1/4" Pin SE, 11.0'.

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species	<u>N. Pine</u>	<u>P. Pole</u>	<u>St. Sign</u>	<u>Gate Post</u>
Diameter	<u>10"</u>	_____	<u>Post</u>	_____
Bearing	<u>S30°W</u>	<u>S38°E</u>	<u>N50°E</u>	<u>N61°W</u>
Distance	<u>76.52*</u>	<u>70.00*</u>	<u>55.99*</u>	<u>56.17*</u>

Bearing Trees, Reference Objects

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed Nov 2003 By B. G. G. #17253
Location filed _____
Monument Cert. of Sec. shows Mon. found

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____