


Index No. V 17

CASS COUNTY LAND CORNER RECORD

T. 138 R. 32 M. 5TH Coordinates: X _____ Y _____
NE 34 Corner common to sections 26, 27, 34, 35



EXISTING SURVEYS

Original Government Survey

Year surveyed 1870

Original monument Post

Original Evidence Found

Year of search _____ By _____

Monument found _____

Species	Bearing Trees			
	N. Pine	N. Pine	N. Pine	ASPEN
Diameter	<u>16"</u>	<u>13"</u>	<u>14"</u>	<u>4"</u>
Bearing	<u>S13W</u>	<u>S32E</u>	<u>N62 1/2 E</u>	<u>N32W</u>
Distance	<u>33 LKS.</u>	<u>81 LKS</u>	<u>28 LKS</u>	<u>14 LKS</u>

Original Bearing Trees Found

Species _____

Diameter _____

Bearing _____

Distance _____

Subsequent Corner Restoration

Year surveyed 1910 By HARRY S. TROOD

Location filed COUNTY SURVEY RECORD BOOK "A" P. 108-109

Monument FND STUMP OF 16" N. Pine S13W 21.8' SET
8x8x36" STONE

1919 - E. B. HURST, COUNTY BOOK "C" P. 159 FND CONCRETE POST
COUNTY BOOK "C" P. 702 CONCRETE MONUMENT

Evidence of Subsequent Corner Restoration

Year of search 8/01 By MaDOT

Found Concrete monument, set
CIM over concrete, down 0.3 in
gravel road, 323' ± W. of Hwy #64.

Bearing Trees, Reference Objects

Species _____

Diameter _____

Bearing _____

Distance _____

Bearing Trees, Reference Objects

Tri. Oak	P. Pole	N. Pine
<u>NE</u>	<u>SW</u>	<u>NW</u>
<u>105.26'*</u>	<u>41.87'*</u>	<u>71.85'*</u>

*distance to SRP

V-17

Subsequent Corner Restoration

Year surveyed Nov 2003 By B. Gering #17253

Location filed _____

Monument Cert. of Surv. shows ^{post iron} ~~mark~~ found

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____