


Index No. V 23

CASS COUNTY LAND CORNER RECORD

T. 138 R. 32 M. 5th Coordinates: X _____ Y _____
N¹/₄ 36 Corner common to sections 25, 36



EXISTING SURVEYS

Original Government Survey

Year surveyed 1870
Original monument POST

Species	Bearing	Trees
<u>Bl. Pine</u>	<u>W.</u>	<u>BIRCH</u>
<u>8"</u>	<u>5"</u>	
<u>S14¹/₂W</u>	<u>N70¹/₂W</u>	
<u>65 LKS.</u>	<u>19 LKS.</u>	

Original Evidence Found

Year of search _____ By _____
Monument found _____

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1919 By E. B. HORST
Location filed COUNTY BOOK "C" P. 159
Monument SET SMALL I.M.

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____