


Index No. A 3

CASS COUNTY LAND CORNER RECORD

T. 139 R. 25 M. 5TH Coordinates: X          Y           
N 1/4 6 Corner common to sections 6 AND 31-140-25



EXISTING SURVEYS

**Original Government Survey**

Year surveyed 1863

Original monument POST

**Bearing Trees**

Species	<u>Y. PINE</u>	<u>Y. PINE</u>	<u>        </u>
Diameter	<u>12"</u>	<u>18"</u>	<u>        </u>
Bearing	<u>N 61 E</u>	<u>S 25 E</u>	<u>        </u>
Distance	<u>193 LKS</u>	<u>249 LKS</u>	<u>        </u>

**Original Evidence Found**

Year of search          By         

Monument found         

**Original Bearing Trees Found**

Species	<u>        </u>	<u>        </u>	<u>        </u>
Diameter	<u>        </u>	<u>        </u>	<u>        </u>
Bearing	<u>        </u>	<u>        </u>	<u>        </u>
Distance	<u>        </u>	<u>        </u>	<u>        </u>

**Subsequent Corner Restoration**

Year surveyed 1937 By CCC

Location filed Lake Washburn BK#1 P14

Monument SET APP. 1/4 POST 40 CH FROM WEST

**Bearing Trees, Reference Objects**

Species	<u>        </u>	<u>        </u>	<u>        </u>
Diameter	<u>        </u>	<u>        </u>	<u>        </u>
Bearing	<u>        </u>	<u>        </u>	<u>        </u>
Distance	<u>        </u>	<u>        </u>	<u>        </u>

**Evidence of Subsequent Corner Restoration**

Year of search          By         

**Bearing Trees, Reference Objects**

Species	<u>        </u>	<u>        </u>	<u>        </u>
Diameter	<u>        </u>	<u>        </u>	<u>        </u>
Bearing	<u>        </u>	<u>        </u>	<u>        </u>
Distance	<u>        </u>	<u>        </u>	<u>        </u>

**Subsequent Corner Restoration**

Year surveyed          By         

Location filed         

Monument         

**Evidence of Subsequent Corner Restoration Found**

Year of search          By         

Re monumentation certificate prepared          By         

Filed at          Date