


Index No. E13

CASS COUNTY LAND CORNER RECORD

T. 139 R. 25 M. 5TH Coordinates: X _____ Y _____
NE 9 Corner common to sections 3, 4, 9, 10



EXISTING SURVEYS

Original Government Survey

Year surveyed 1863
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

	Bearing	Trees	
Species	<u>FIR</u>	<u>ASPEN</u>	<u>W. PINE</u>
Diameter	<u>6"</u>	<u>10"</u>	<u>11"</u>
Bearing	<u>N55E</u>	<u>S70W</u>	<u>N38W</u>
Distance	<u>14 LKS.</u>	<u>4 LKS</u>	<u>36 LKS</u>

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1937 By CCC
Location filed Washburn Lake - Bk # 2 P. 49
Monument at 5280' from east - set 4" ASPEN Post -
APPROX Cor.

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____
Filed at _____

By _____
Date _____