


Index No. J 13

CASS COUNTY LAND CORNER RECORD

T. 139 R. 25 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
NE 16 Corner common to sections 9, 10, 15, 16



EXISTING SURVEYS

Original Government Survey

Year surveyed 1863  
Original monument Post

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

	Bearing	Trees	
Species	<u>TAM.</u>	<u>TAM.</u>	<u>TAM.</u>
Diameter	<u>5"</u>	<u>8"</u>	<u>7"</u>
Bearing	<u>N40E</u>	<u>N45W</u>	<u>S45E</u>
Distance	<u>16 LKS.</u>	<u>16 LKS</u>	<u>23 LKS</u>

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

O = Corner

Subsequent Corner Restoration

Year surveyed 1937 (June) By CC  
Location filed Washburn Lake BK#1 R67  
Monument Set approx cor 5280' from east set  
4" Tam post with metal tag  
10-21-1937 Tie to restoration man 13.5' east  
and 61.0' south

Evidence of Subsequent Corner Restoration

Year of search 1937 By CC  
Washburn Lake - BK#8  
Find stumps of NE, SE & SW B.T.'s set 1" x 54"  
1 1/2" w/ 2 1/4" steel cap 7139  
9/10  
16/15

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Bearing Trees, Reference Objects

<u>Balsam</u>	<u>Bl Spruce</u>	<u>Balsam</u>	<u>Birch</u>
<u>6 1/2"</u>	<u>5 1/2"</u>	<u>4 3/4"</u>	<u>5 1/4"</u>
<u>N 33 1/2 E</u>	<u>S 65 E</u>	<u>S 68 1/2 W</u>	<u>N 69 W</u>
<u>22.6'</u>	<u>100.9'</u>	<u>83.3'</u>	<u>74.7'</u>

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Remonumentation certificate prepared \_\_\_\_\_  
Filed at \_\_\_\_\_

By \_\_\_\_\_  
Date \_\_\_\_\_