


Index No. J 25

CASS COUNTY LAND CORNER RECORD

T. 139 R. 25 M. 5th Coordinates: X _____ Y _____
NE 13 Corner common to sections 12, 13



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1863
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species	<u>FIR</u>	<u>BIRCH</u>	_____
Diameter	<u>3"</u>	_____	_____
Bearing	<u>S45W</u>	<u>N75W</u>	_____
Distance	<u>25 LKS.</u>	<u>23 LKS</u>	_____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1911 By JOHN CUPP
Location filed COUNTY SURVEY RECORD BOOK "A" P 349-352
Monument FIND OLD GOVT B.T.S: BIRCH N75W 15.2', Pines OF 3" FIR S45W 16.5'

Evidence of Subsequent Corner Restoration

Year of search 1937 By CCC
Washburn Lake - BK# 1 P. 63
Start at APPROX Corner.
1938 - BK# 20 corner in Road - Yellow tag on telephone post

also on microfilm - roll 115 BK 74 P. 13

Bearing Trees, Reference Objects

Species	<u>BIRCH</u>	<u>MARLE</u>	_____
Diameter	<u>12"</u>	<u>9"</u>	_____
Bearing	<u>S53W</u>	<u>S64-37E</u>	_____
Distance	<u>36.77'</u>	<u>33.42'</u>	_____

Bearing Trees, Reference Objects

_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____