


Index No. L9

CASS COUNTY LAND CORNER RECORD

T. 139 R. 25 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
E1/4 17 Corner common to sections 16, 17



EXISTING SURVEYS

Original Government Survey

Year surveyed 1863  
Original monument POST

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees

Species	<u>TAM</u>	<u>TAM</u>	_____	_____
Diameter	<u>10"</u>	<u>10"</u>	_____	_____
Bearing	<u>N20E</u>	<u>S45W</u>	_____	_____
Distance	<u>23 LKS</u>	<u>33 LKS</u>	_____	_____

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1936 By CCC  
Location filed Washburn Lake - BK#3 P.9  
Monument at 41 CH. from S. Sq Birch  
1937- BK# B. Find both B, 15- but SW BIT in error  
set 54" x 1 1/2" I.P. 2 1/2' m ground w/cap T139  
17/16  
R25

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_

Bearing Trees, Reference Objects

Species	<u>Jam Stump</u>	<u>Jam windfall</u>	<u>Balsam</u>	<u>Balsam</u>
Diameter	<u>orig B.T.</u>	<u>orig B.T.</u>	<u>5 1/2"</u>	<u>6"</u>
Bearing	<u>N16 1/4 E</u>	<u>S75W</u>	<u>N82E</u>	<u>S80 1/2 W</u>
Distance	<u>15.2'</u>	<u>15.2'</u>	<u>14.85'</u>	<u>18.45'</u>

Bearing Trees, Reference Objects

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
Filed at \_\_\_\_\_ Date \_\_\_\_\_