


Index No. N 19

CASS COUNTY LAND CORNER RECORD

T. 139 R. 25 M. 5th Coordinates: X _____ Y _____
N 14 23 Corner common to sections 14, 23



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1863
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees	
Species <u>W. BIRCH</u>	<u>W. BIRCH</u>
Diameter <u>6"</u>	<u>6"</u>
Bearing <u>S14E</u>	<u>N14W</u>
Distance <u>11 LKS</u>	<u>19 LKS</u>

Original Bearing Trees Found

Species _____	_____
Diameter _____	_____
Bearing _____	_____
Distance _____	_____

Subsequent Corner Restoration

Year surveyed 1910 By A.W. Moulster
Location filed COUNTY SURVEY RECORD BOOK "A" P. 46-318
Monument Find 1 ovp Govt B.T: 6" W. Birch S14E
7.3' SET POST

Evidence of Subsequent Corner Restoration

Year of search 1937 By CCC
Washburn Lake - BK # 1 P. 60
Set Approx Cor 2640' from east

also on microfilm Roll 105 BK 48 P. 81-82

Ties to E 1/4 Below - Roll 105 - BK 48 P. 90

Bearing Trees, Reference Objects

Species <u>W. Birch</u>	<u>W. Birch</u>	_____
Diameter <u>10"</u>	<u>10"</u>	_____
Bearing <u>S13-30W</u>	<u>N12-11W</u>	_____
Distance <u>46.85'</u>	<u>70.17'</u>	_____

Bearing Trees, Reference Objects

<u>W. Pine</u>	<u>N. Pine</u>	_____
<u>14"</u>	<u>12"</u>	_____
<u>S60W</u>	<u>S70E</u>	_____
<u>10.37'</u>	<u>35.7'</u>	_____

N-19

Subsequent Corner Restoration

Year surveyed 1911 By Curo
Location filed microfilm-roll 115 BK 74 P. 8
Monument Find 4x4 post set by Maulster
for corner from gov't B.T.'s

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

7/04 - CCSO set 7/0" 001P, down
0.3', 2'± N. of & Co. Rd # 58 at
A10 record distance.

<u>20" N. Pine</u>	<u>N55°W</u>	<u>56.07'*</u>
<u>16" N. Pine</u>	<u>N54°E</u>	<u>40.64'*</u>
<u>8" Maple</u>	<u>S16°W</u>	<u>43.68'*</u>

*distance to double head nail

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____