Index No. N 21

CASS COUNTY LAND CORNER RECORD

T. 139 R. 25 M. 5TH Coordinates: X _____ Y _____

NE 23 Corner common to sections 13, 14, 23, 24



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1863

Original monument Post

Original Evidence Found

Year of search _____ By _____

Monument found _____

Bearing Trees

Species	TAM.	TAM	TAM.	W. BIRCH
Diameter	3"	6"	10"	7"
Bearing	S 20 W	S 62½ E	N 85 E	N 76½ W
Distance	60 LKS.	110 LKS	240 LKS	450 LKS

Original Bearing Trees Found

Species				
Diameter				
Bearing				
Distance				

Subsequent Corner Restoration

Year surveyed 1910 By A.W. MOULSTER

Location filed COUNTY SURVEY RECORD BOOK "A" P 346-348

Monument FND 3 OLD GOVT TAM BITS FND STAKE, SET NEW STAKE

also on microfilm - Roll 105 BK 48 P. 84

Evidence of Subsequent Corner Restoration

Year of search 1937 By CCC

Washburn Lake - BK #1 P 60

Approx Cor.

1941 - CCC - Emily Lome Refuge Book P. 1

Start East from intersection of roads.

Bearing Trees, Reference Objects

Species	TAM	TAM	TAM	
Diameter	7"	6"	4"	
Bearing	N 82-56 E	S 72-52 E	S 27-43 W	
Distance	123.15'	67'	~~56.60'~~ 66.50'	

Bearing Trees, Reference Objects

N-21

Subsequent Corner Restoration

Year surveyed 1911 By Curo

Location filed microfilm - roll 115 BK 74 P. 10

Monument Fnd 4x4 post set by Moulster from B.T.'S

Mar 2003 Found 1" OD pin, down 0.1', near Pl Co Rd #58, 3'± East of driveway

* 10" Tamarack N 40° W 77.98'

* 9" Tamarack N 25° E 72.28'

* 8" W. Oak S 30° W 62.50'

* - Dist. to dbl hd. nail

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____