


Index No. N 3

CASS COUNTY LAND CORNER RECORD

T. 139 R. 25 M. 574 Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
N 1/4 19 Corner common to sections 18, 19



EXISTING SURVEYS

Original Government Survey

Year surveyed 1863  
Original monument Post

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees  
Species JAM ASH  
Diameter 10" 6"  
Bearing N3E S35W  
Distance 69 LKS 50 LKS

Original Bearing Trees Found

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed 1912 By JOHN CURO  
Location filed COUNTY SURVEY RECORD BOOK "B" P. 180-182  
Monument FIND OLD CORNER BIT: 6" ASH S35W 50 LKS.  
SET 2x4x30" PUB.  
1920, BEN CLARK, COUNTY BOOK "C" P. 541 FIND POST IN ROAD  
SET 2x4x18" IRON MONUMENT

Evidence of Subsequent Corner Restoration

Year of search 1937 By CCC  
Wash burn Lake - BK # 1 P. 64  
Fnd orig B.T.: 8" Ash S32W 40' - at 2600'  
West - Set approx 2" Aspen w/ metal tag at  
2640 West  
BK # 3 P. 8 Tag on 6" Ash - old scribiny S45W 41'  
Fnd 1" Bearing Trees, Reference Objects  
1926 BUCKLER MAP SHOWS IN PLACE

Bearing Trees, Reference Objects

Species ASH ASH CEGAR  
Diameter 9" 6" 6"  
Bearing N47-35W S17-30W N17-30E  
Distance 30' 39.3' 43.1'  
1912 B.T.S. 1920 B.T.S.

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Remonumentation certificate prepared \_\_\_\_\_

By \_\_\_\_\_

Filed at \_\_\_\_\_

Date \_\_\_\_\_