


Index No. N 9

CASS COUNTY LAND CORNER RECORD

T. 139 R. 25 M. 5TH Coordinates: X _____ Y _____
NE 20 Corner common to sections 16, 17, 20, 21



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1863
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Species	Bearing	Trees	Distance
<u>TAM</u>	<u>TAM</u>	<u>TAM</u>	<u>TAM</u>
<u>4"</u>	<u>3"</u>	<u>6"</u>	<u>4"</u>
<u>N84E</u>	<u>S45E</u>	<u>S17W</u>	<u>N68W</u>
<u>38 LKS</u>	<u>44 LKS</u>	<u>50 LKS</u>	<u>7 LKS</u>

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1937 By CCC
Location filed Washburn Lake - BK # 1 P 62
Monument at 5280 from east set Approx Cor - 4" Tam
Post - End Orig # or 222' N & 117' West
total dist = 5397' from east

Evidence of Subsequent Corner Restoration

Year of search 1937 By CCC
Washburn Lake - BK # 3 P 6
2" sq Poplar stake beside road

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Bearing Trees, Reference Objects

Tag on Poplar	Tag on Tam
<u>16"</u>	<u>8"</u>
<u>S74W</u>	<u>S69E</u>
<u>67'</u>	<u>72'</u>

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____