


Index No. T5

CASS COUNTY LAND CORNER RECORD

T. 139 R. 25 M. 5TH Coordinates: X _____ Y _____
E 1/4 30 Corner common to sections 29, 30



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1863
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species SPRUCE TAM _____
Diameter 6" 7" _____
Bearing N25E N30W _____
Distance 23 LKS 45 LKS _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed 1936 By CCC
Location filed Washburn Lake - BK #3 P. 2
Monument at 40 CH from S. set approx 1/4 corner

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

1986 BUCKLER MAP SHOWS MALACE

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____