


Index No. V 5

CASS COUNTY LAND CORNER RECORD

T. 139 R. 25 M. 5TH Coordinates: X _____ Y _____
NE 31 Corner common to sections 29, 30, 31, 32



EXISTING SURVEYS

Original Government Survey

Year surveyed 1863
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species	<u>J. PINE</u>	<u>J. PINE</u>	<u>ASPEN</u>	<u>ASPEN</u>
Diameter	<u>12"</u>	<u>6"</u>	<u>8"</u>	<u>5"</u>
Bearing	<u>N12E</u>	<u>N12W</u>	<u>SRE</u>	<u>S23/4W</u>
Distance	<u>233 LKS</u>	<u>214 LKS</u>	<u>519 LKS</u>	<u>529 LKS</u>

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1909 By JOHN CURE
Location filed COUNTY SURVEY RECORD BOOK '9' P342-345
Monument FIND 1 OLD CANT B.T. SET CORNER

also on microfilm - roll 115 BK95 P. 5-6

Evidence of Subsequent Corner Restoration

Year of search 1937 By CCC
Washburn Lake - BK#1 P53
Find 2" I.P. 5287' East Post is 26' from
culvert w/ post beside - no cap on I.P.
BK#3 P.1 Find I.P. in center of road 5308' from W.
1938 - BK#20 Find iron pipe in road 2" under surface

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Bearing Trees, Reference Objects

_____	_____	_____
_____	_____	_____
_____	_____	_____
_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1966 By DNR - Engineering
Location filed Map notes in file
Monument Found I.P. in place

1986 BUCKLER MAP SHOWS INPLACE

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
PLAT - JACKSON'S OLD LODGE SITE
F.C. JACKSON 1955

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____