


Index No. V 7

CASS COUNTY LAND CORNER RECORD

T. 139 R. 25 M. 5TH Coordinates: X _____ Y _____
N 1/4 32 Corner common to sections 29, 32



EXISTING SURVEYS

Original Government Survey

Year surveyed 1863
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species Y. PINE Y. PINE
Diameter 11" 8"
Bearing N1W S32W
Distance 43 LKS 54 LKS

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed 1937 By CCC
Location filed Washburn Lake BK#1 P.54
Monument Set 3 1/2" soft maple 2640' E from
NE 31
BK#3 P.3 Find old post 40 ch. from west

Evidence of Subsequent Corner Restoration

Year of search 1966 By DNR-Engineering
Map notes in file

Found 1 P. in place

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

4" Birch 5" Birch
Nail i B.C. Nail i B.C.
S5W W
20.60' 21.92'

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
PLAT - JACKSON'S OLD LODGE SITE
F.C. JACKSON 1955

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____