


T. 139 R. 25 M. 5TH Coordinates: X _____ Y _____
SE 35 Corner common to sections 35, 36



○ = Corner

EXISTING SURVEYS

Original Government Survey
 Year surveyed 1863
 Original monument Post

Original Evidence Found
 Year of search _____ By _____
 Monument found _____

	Bearing Trees			
Species	<u>TAM</u>	<u>TAM</u>	<u>TAM</u>	<u>TAM</u>
Diameter	<u>5"</u>	<u>4"</u>	<u>6"</u>	<u>7"</u>
Bearing	<u>N58 1/2 W</u>	<u>N39 E</u>	<u>S17 E</u>	<u>S55 W</u>
Distance	<u>13 LKS</u>	<u>22 LKS</u>	<u>62 LKS</u>	<u>29 LKS</u>

Original Bearing Trees Found
 Species _____
 Diameter _____
 Bearing _____
 Distance _____

Subsequent Corner Restoration
 Year surveyed 1937 By CCC
 Location filed Washburn Lake - BK# 2 P. 20
 Monument End 4" Cor. Stake and B.T. - N39E 22 LKS
80 ft from east
1940 - BK# 19 P. 18 at 5280' from east End 1/4" 139'
North - also end 1937 - CCC B.T.S

Evidence of Subsequent Corner Restoration
 Year of search 1937 By CCC
Washburn Lake - BK# 2
End remains of all 4 B.T.S - set 1 1/2 x 5/4" 1/4", 2 1/2"
in ground w/ 2 1/4" steel cap
T139 R25
35/36
211
T138 R25

Bearing Trees, Reference Objects
 Species _____
 Diameter _____
 Bearing _____
 Distance _____

Bearing Trees, Reference Objects			
<u>W. Pine</u>	<u>Birch</u>	<u>Elm</u>	<u>Birch</u>
<u>15"</u>	<u>11 1/2"</u>	<u>12"</u>	<u>9 1/2"</u>
<u>N1 1/2 W</u>	<u>S64 1/2 E</u>	<u>S40 W</u>	<u>N79 1/2 W</u>
<u>48'</u>	<u>84.9'</u>	<u>129'</u>	<u>62.3'</u>
<u>scribed</u>	<u>scribed</u>	<u>scribed</u>	<u>scribed</u>

267' w - tag on tree beside trail

Subsequent Corner Restoration
 Year surveyed Feb 1998 By C.C. Land Dept - A.R. J.L.
 Location filed _____
 Monument now found exc cond

Evidence of Subsequent Corner Restoration Found
 Year of search _____ By _____

Mar 2003 Found 1 1/4" OPIP w/ flat
screw on cap, up 0.8' area
has been logged off.

- * 4" Maple N15° E 30.80'
- * 5" Balsam S75° E 63.45'
- * 4" Ash S10° W 29.50'
- * - Dist. to 20 d nail

Remonumentation certificate prepared _____
 Filed at _____

By _____
 Date _____