


T. 139 R. 26 M. 5TH Coordinates: X NE 1 Y NE 1
Corner common to sections 1 AND 6-139-25 AND 31-140-25
AND 36-140-26



EXISTING SURVEYS

Original Government Survey

Year surveyed 1863
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Species	Bearing Trees			
	W. PINE	W. PINE	W. PINE	W. PINE
Diameter	<u>30"</u>	<u>24"</u>	<u>30"</u>	<u>22"</u>
Bearing	<u>N50E</u>	<u>S48E</u>	<u>S22W</u>	<u>N38W</u>
Distance	<u>116 LKS.</u>	<u>103 LKS.</u>	<u>31 LKS.</u>	<u>36 LKS.</u>

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1920 By BEN CLARK
Location filed COUNTY BOOK "C" P. 570
Monument FIND SW & NW B.T. STUMPS AND 2 OTHER B.T.S.
15" W. PINE N80E 53 LKS. 12" W. PINE S89E 44 LKS.
SET 2 1/2 X 36" CAPPED IRON.

Evidence of Subsequent Corner Restoration

Year of search 1937 By CCC
Washburn Lake - BK#2 P. 39
at 5274' from west - Find 2" 1.8" 2-4" post
BK#2 P. 40 5272' from North
Scribed 6" Ash N74W 166'
BK#3 P. 69 - iron pipe sec. cor.

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
<u>ELM</u>	<u>8"</u>	<u>N6W</u>	<u>122.4'</u>
<u>oak</u>	<u>5"</u>	<u>S9W</u>	<u>135.6'</u>
_____	_____	_____	_____
_____	_____	_____	_____

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____