


Index No. E 11

CASS COUNTY LAND CORNER RECORD

T. 139 R. 26 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
N 1/4 9 Corner common to sections 4, 9



EXISTING SURVEYS

Original Government Survey

Year surveyed 1863  
Original monument Post

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees

Species	<u>W. PINE</u>	<u>W. PINE</u>	_____	_____
Diameter	<u>15"</u>	<u>16"</u>	_____	_____
Bearing	<u>S 27 W</u>	<u>N 21 E</u>	_____	_____
Distance	<u>25 LKS.</u>	<u>15 LKS.</u>	_____	_____

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 4/25/88 By John Walker / DNR  
Location filed Cert. Filed Doc. # 312277  
Monument Set 1 1/2" x 4" iron pipe with square  
aluminum cap up 0.8" in swamp.

6-13

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_

Bearing Trees, Reference Objects

Species	<u>Ash</u>	<u>Birch</u>	<u>White Pine</u>	<u>Maple Triple</u>
Diameter	<u>7"</u>	<u>3"</u>	<u>29"</u>	<u>6"</u>
Bearing	<u>292°</u>	<u>50°</u>	<u>145°</u>	<u>228°</u>
Distance	<u>7.04'</u>	<u>16.49'</u>	<u>70.17'</u>	<u>11.71'</u>

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By 6-13  
5-22-89 Cert. Filed by John Walker, RLS 16098  
Doc. # 312277.

Remonumentation certificate prepared \_\_\_\_\_

By \_\_\_\_\_

Filed at \_\_\_\_\_

Date \_\_\_\_\_