Index No. E 8-9

CASS COUNTY LAND CORNER RECORD

T. 139 R. 26 M. 5TH Coordinates: X _____ Y _____

MC # 48 Corner common to sections 5, 8



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1863

Original monument POST

Original Evidence Found

Year of search _____ By _____

Monument found _____

Bearing Trees

Species	W. PINE	N. PINE
Diameter	18"	7"
Bearing	S25E	N20E
Distance	19 LKS	35 LKS

Original Bearing Trees Found

Species				
Diameter				
Bearing				
Distance				

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species				
Diameter				
Bearing				
Distance				

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

PLAT - PATTERSON LAKE SHORE LOTS

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____