


Index No. J 25

CASS COUNTY LAND CORNER RECORD

T. 139 R. 26 M. 5TH Coordinates: X _____ Y _____
NE 13 Corner common to sections 12, 13 and 7, 18-139-25



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1863
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

| | Bearing | Trees | |
|----------|---------------|---------------|----------------|
| Species | <u>ASH</u> | <u>MAPLE</u> | <u>W. PINE</u> |
| Diameter | <u>8"</u> | <u>5"</u> | <u>20"</u> |
| Bearing | <u>N60E</u> | <u>S13E</u> | <u>S65W</u> |
| Distance | <u>22 LKS</u> | <u>27 LKS</u> | <u>53 LKS</u> |

Original Bearing Trees Found

| | | | |
|----------|-------|-------|-------|
| Species | _____ | _____ | _____ |
| Diameter | _____ | _____ | _____ |
| Bearing | _____ | _____ | _____ |
| Distance | _____ | _____ | _____ |

Subsequent Corner Restoration

Year surveyed 1920 By Ben Clark
Location filed COUNTY BOOK C P. 541
Monument SET CORNER PROPORTIONALLY SET 2 1/2 x 36" CAPPED I.M.

Evidence of Subsequent Corner Restoration

Year of search 1936? By CCC
Washburn Lake - BK # 3 P. 67
at 79 CH. from west - iron pipe sec. cor.
10" N. line N62W 81'
BK # 4 P. 1 - I.P.

Bearing Trees, Reference Objects

Species N. PINE
Diameter 8"
Bearing S63E
Distance 69.6'

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____