


Index No. N 5

CASS COUNTY LAND CORNER RECORD

T. 139 R. 26 M. 5TH Coordinates: X _____ Y _____
NE 19 Corner common to sections 17, 18, 19, 20



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1863
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Species	Bearing	Trees
<u>ASPEN</u>	<u>ASPEN</u>	
Diameter <u>10"</u>	<u>10"</u>	
Bearing <u>N75E</u>	<u>S45W</u>	
Distance <u>112 LKS</u>	<u>40 LKS</u>	

Species	Bearing	Trees
_____	_____	_____
Diameter _____	_____	_____
Bearing _____	_____	_____
Distance _____	_____	_____

Subsequent Corner Restoration

Year surveyed 1940 By CCC
Location filed Washburn Lake - BK#4
Monument Set APPROX SEC. COR. at 52.80 from N BK#8 - Set approx cor 29.5' E. of N-S line and 112.7' N of E-W line.

Evidence of Subsequent Corner Restoration

Year of search 1964 By Co Hunt Dept.
Co RD # 48
14" iron rod w/ 2 - 5' posts 1375' S. of rd
1986 BOCKLER MAP SHOWS IN PLACE

Bearing Trees, Reference Objects

Species	Bearing	Reference Objects
_____	_____	_____
Diameter _____	_____	_____
Bearing _____	_____	_____
Distance _____	_____	_____

Bearing Trees, Reference Objects

Species	Bearing	Reference Objects
_____	_____	_____
Diameter _____	_____	_____
Bearing _____	_____	_____
Distance _____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Plat - Second Add. to Birch Bay on Washburn Lake
- Dan Coulter 1982

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____