


Index No. N 7

CASS COUNTY LAND CORNER RECORD

T. 139 R. 26 M. 5TH Coordinates: X _____ Y _____
N 1/4 20 Corner common to sections 17, 20



EXISTING SURVEYS

Original Government Survey

Year surveyed 1863
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Species	Bearing	Trees
<u>Y. Pine</u>	<u>Y. Pine</u>	
<u>12"</u>	<u>11"</u>	
<u>N50W</u>	<u>S11W</u>	
<u>35 LKS</u>	<u>33 LKS</u>	

Original Bearing Trees Found

Species	Diameter	Bearing	Distance

Subsequent Corner Restoration

Year surveyed 1964 By Co Hwy Dept
Location filed Co Op # 48
Monument 1 1/2" W. in place ± 1333' S. of road

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

1986 BUCKLER MAP SHOWS IN PLACE

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
PLAT - BIRCH BAY ON WASHBURN LAKE
DONALD COULTER 1976

PLAT - FIRST ADDITION TO BIRCH BAY ON WASHBURN LAKE
DONALD COULTER 1977

Plot - Second Add. to Birch Bay on Washburn Lake
Don Coulter 1982

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____