


Index No. U-V 17

CASS COUNTY LAND CORNER RECORD

T. 139 R. 26 M. 5TH Coordinates: X _____ Y _____
MC # 13 Corner common to sections 26,27



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1863
Original monument Post

Bearing Trees	
Species <u>WILLOW</u>	<u>W. CEDAR</u>
Diameter <u>5"</u>	<u>10"</u>
Bearing <u>N5W</u>	<u>N22E</u>
Distance <u>100 LKS</u>	<u>71 LKS</u>

Original Evidence Found

Year of search _____ By _____
Monument found _____

Original Bearing Trees Found

Species _____	_____	_____
Diameter _____	_____	_____
Bearing _____	_____	_____
Distance _____	_____	_____

Subsequent Corner Restoration

Year surveyed 1936? By CCC
Location filed Washburn Lake - BK #3 P 59
Monument M.C. 7 CH. N. OF NE 34 (in lake)
5 CH. S. OF M.C. to North

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species _____	_____	_____
Diameter _____	_____	_____
Bearing _____	_____	_____
Distance _____	_____	_____

Bearing Trees, Reference Objects

_____	_____	_____
_____	_____	_____
_____	_____	_____
_____	_____	_____

Subsequent Corner Restoration

Year surveyed 7/30/91 By James Nielsen/MN DOT
Location filed Cert. Filed 6-2-93 Doc. #34775?
Monument On 7/30/91 Found 1 3/4" Iron pipe On
2/22/93 Set MHD cast iron monument.
Ties: 18" Spruce N85W 105.50'; 24" Twia
Willows S30E 14.25'; 12" Willow S75W
94.56'

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____
Filed at _____

By _____
Date _____