


T. 139 R. 26 M. 5TH Coordinates: X _____ Y _____
514 35 Corner common to sections 35



EXISTING SURVEYS

Original Government Survey

Year surveyed 1863

Original monument Post

Species	Bearing	Trees
<u>PINE</u>	<u>N57E</u>	<u>W. BIRCH</u>
<u>12"</u>	<u>55W</u>	<u>10"</u>
<u>16 LKS</u>	<u>35 LKS</u>	

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species	Bearing	Distance
_____	_____	_____
_____	_____	_____
_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1908 By JOHN CURD

Location filed COUNTY SURVEY RECORD BOOK "A" P. 390-398

Monument END ORIG. B.T. 10" W. BIRCH 55W 23.1'
STUMP OF NE PINE

also on microfilm - vol 1115 BK 95 P. 17-18

Bearing Trees, Reference Objects

Species	Bearing	Distance
_____	_____	_____
_____	_____	_____
_____	_____	_____

Evidence of Subsequent Corner Restoration

Year of search 1939 By CCC

Washburn Lake - BK # 17 P. 57 at 2640' from W -
Set approx 1/4 cor.

Bearing Trees, Reference Objects

Species	Bearing	Distance
_____	_____	_____
_____	_____	_____
_____	_____	_____

2-19

Subsequent Corner Restoration

Year surveyed 1981 By DNR-Engineering

Location filed Map notes in file

Monument End 2" 1.1" w/ 3" cap up 1.5'
Stamped 1/4 35
5.2

Ties:

- 3' Maple N 87° E 21.55' DNR DISC S. side
- 10" Birch 557° E 19.68' DNR DISC NE side
- 11" Maple 570° W 37.84' DNR DISC S. side
- 6" W. oak N 70° W 37.78' DNR DISC NE side

1970 ± Con. (outlet) (From Crow Wing Co) 505/4
found 1 1/2" 1.1" in place with 3" cap

- Poplar 12" 588° E 47.2'
- Poplar 12" 523-50° E 46.3'
- Poplar 10" N 42-20° W 28.8'
- Poplar 12" 550° W 35.85'
- Tree 10" 571-30° W 37.5'

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

1987 - Certificate - John Walker - DNR
Doc # 300476
Same information as 1981 DNR information