


Index No. I 23

CASS COUNTY LAND CORNER RECORD

T. 139 R. 26 M. 5TH Coordinates: X _____ Y _____
514 36 Corner common to sections 36



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1863
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Species	<u>ASPEN</u>	Bearing	<u>ASPEN</u>	Trees	_____
Diameter	<u>6"</u>		<u>6"</u>		_____
Bearing	<u>N7W</u>		<u>SOUTH</u>		_____
Distance	<u>16 LKS</u>		<u>14 LKS</u>		_____

Original Bearing Trees Found	_____	_____	_____
Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1937 By CCC
Location filed Washburn Lake BK#1 P.16
Monument Set app. 1/4 Post 40 CA from west

Evidence of Subsequent Corner Restoration

Year of search 1939 By CCC
Washburn Lake - BK#17 P.59 at 2640' from W -
Set approx 1/4 cor. Find 4" sq. hardwood stake
on brushed line at 2530' from W.

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Bearing Trees, Reference Objects

_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____