


Index No. Z 25

CASS COUNTY LAND CORNER RECORD

T. 139 R. 26 M. 5TH Coordinates: X _____ Y _____
SE 36 Corner common to sections 36 AND 31-139-25



EXISTING SURVEYS

Original Government Survey
Year surveyed 1863
Original monument POST

Original Evidence Found
Year of search _____ By _____
Monument found _____

Bearing Trees			
Species	W. PINE	W. BIRCH	W. BIRCH
Diameter	<u>20"</u>	<u>7"</u>	<u>8"</u>
Bearing	<u>S59E</u>	<u>N58E</u>	<u>S20W</u>
Distance	<u>17 LKS.</u>	<u>14 LKS.</u>	<u>21 LKS.</u>

Original Bearing Trees Found			
Species			
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

O = Corner

Subsequent Corner Restoration

Year surveyed 1937 By CCC
 Location filed Washburn Lake DK#1 P.16
 Monument Set App. 1 mile past 80 CH from west
CC# DK#2 P.15 Approx cor 80 CH from N.

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species _____
 Diameter _____
 Bearing _____
 Distance _____

Bearing Trees, Reference Objects

Z-25

Subsequent Corner Restoration

Year surveyed 11-15-1994 By A. KERICK
 Location filed CROW WING CO. DOC. # 477943
 Monument 2" X 3" STEEL TUBE (SQUARE) AND ALUMINUM
STAP

6" BIRCH	<u>S85°E</u>	<u>3.04</u>
9" R. OAK	<u>S35°E</u>	<u>14.85</u>
8" BIRCH	<u>N40°W</u>	<u>18.85</u>
4" MAPLE	<u>WEST</u>	<u>16.89</u>
GPS ECCENTRIC	<u>S30°04'29"W (CWC)</u>	<u>76.77</u>

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____
Filed at _____

By _____
Date _____