


T. 139 R. 26 N. 5TH Coordinates: X _____ Y _____
SE 32 Corner common to sections 32, 33



EXISTING SURVEYS

Original Government Survey

Year surveyed 1863
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Species	Bearing	Trees	Distance
<u>OAK</u>	<u>Linn</u>	<u>W. Pine</u>	<u>OAK</u>
<u>12"</u>	<u>11"</u>	<u>14"</u>	<u>10"</u>
<u>N37E</u>	<u>S70E</u>	<u>S23W</u>	<u>N86W</u>
<u>78 LKS</u>	<u>19 LKS</u>	<u>129 LKS</u>	<u>126 LKS</u>

Original Bearing Trees Found

Species	Bearing	Distance
_____	_____	_____
_____	_____	_____
_____	_____	_____
_____	_____	_____

O = Corner

Subsequent Corner Restoration

Year surveyed 1937 By CC
Location filed Washburn Lake BK#1 P. 31
Monument Set 4' Sq Birch 80 CH from west
1939- BK#17 P. 50 of S333' from E end 1 P. 36" N
of random line - also find B.T. 18" W. line N35W 53'

Evidence of Subsequent Corner Restoration

Year of search 1942 By Louis Knudsen
From Crow Wing Co. Page 29 Book 35

Iron pipe in place

Bearing Trees, Reference Objects

Species	Bearing	Distance
_____	_____	_____
_____	_____	_____
_____	_____	_____
_____	_____	_____

Bearing Trees, Reference Objects

Species	Bearing	Distance
_____	_____	_____
_____	_____	_____
_____	_____	_____
_____	_____	_____

Z-9

Subsequent Corner Restoration

Year surveyed Nov 1978 By Wally Beckley - from Crow
Location filed B135, P148 Wing Co.
Monument Found 1 1/2" Galv. pipe in rock pile, Lin Bass
ESE 1 1/2 ft fence N's E - found remains of
post below pipe
Lin Bass 10" S70E 11.6'
R. oak 12" S40W 17.3'
Basswood 20" S85W 5.15'

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

1975± Don Coulter - from Crow Wing Co.
5/1/93 Found a 1 1/2" Galv. pipe in rock
pile up 1.5'
oak 12" NW 32.05'
oak 12" W 24.25'
oak 12" SW 17.45'
Basswood 10" SE 11.75'