Index No. A 13

CASS COUNTY LAND CORNER RECORD

T. 139 R. 27 M. 5TH Coordinates: X _____ Y _____

NE 4 Corner common to sections 3,4 AND 33,34- T140-27



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1863

Original monument POST

Original Evidence Found

Year of search _____ By _____

Monument found _____

Bearing Trees

Species	ASPEN	J.PINE	J.PINE	J.PINE
Diameter	10"	7"	8"	12"
Bearing	N32W	N5½E	S10E	S86W
Distance	147 LKS	209 LKS	265 LKS	175 LKS

Original Bearing Trees Found

Species				
Diameter				
Bearing				
Distance				

Subsequent Corner Restoration

Year surveyed 1937 By CCC

Location filed Washburn Lake - BK #3 P. 23

Monument at 58.32 from South - Set approx Corner at intersection with township line

1936 - BK # 7 P. 20 Found Sq. Stake 82.70 CH from east 1.78 CH So. of Random line

Bearing Trees, Reference Objects

Species				
Diameter				
Bearing				
Distance				

Evidence of Subsequent Corner Restoration

Year of search 4/9/91 By David Landecker

Found 3"x3" wood post up 30" next to rotted wood post.

Set 5' rod with 3' stabilizer and aluminum cap.

Bearing Trees, Reference Objects

	Jack Pine	Jack Pine	White Pine	
	10"	10"	12"	
	N 6 W	S 5 E	S 78 W	
	119.31'	124.01'	130.50'	

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

6-11-91 Cert Filed by David Landecker Doc. # 329228.

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____