


Index No. A 17

CASS COUNTY LAND CORNER RECORD

T. 139 R. 27 M. 5TH Coordinates: X _____ Y _____
NE 3 Corner common to sections 2, 3 AND 34, 35-140-27



EXISTING SURVEYS

Original Government Survey

Year surveyed 1863
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Original Bearing Trees Found

	Bearing	Trees	
Species	<u>TAM</u>	<u>TAM</u>	<u>TAM</u>
Diameter	<u>4"</u>	<u>4"</u>	<u>4"</u>
Bearing	<u>NBE</u>	<u>S61E</u>	<u>S2 1/2 W</u>
Distance	<u>24 LKS.</u>	<u>29 LKS</u>	<u>41 LKS</u>

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

O = Corner

Subsequent Corner Restoration

Year surveyed 1937 By CCC
Location filed Lake Washburn BK#1 P.25
Monument End cor. 88.78 CH. from South
1936- BK#7 P.19 at 60 CH from E - Set
4" Tam Stake Approx Cor.

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____