


Index No. C R 1

CASS COUNTY LAND CORNER RECORD

T. 139 R. R7 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
E 1/4 R Corner common to sections 112



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1864  
Original monument POST

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees

Species SPRUCE TAM.  
Diameter 7" 5"  
Bearing EAST S20W  
Distance 6 LKS. 14 LKS.

Original Bearing Trees Found

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed 1913 By HARRY TODD  
Location filed COUNTY SURVEY RECORD BOOK A P576-580  
Monument SET CORNER, CURD BOOK 173 PAGES  
53-75 MF ROLL 12

Evidence of Subsequent Corner Restoration

Year of search 1936 By CCC  
Washburn Lake - BR# 7 P. 6  
at 42.95 CH. N. OF SE 2 - 1/4 corner

Bearing Trees, Reference Objects

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Bearing Trees, Reference Objects

Tam stub  
8.5"  
S55W  
68 LKS  
scribed B.T 1/4 S.B.T.

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
Filed at \_\_\_\_\_ Date \_\_\_\_\_