


Index No. P 21

CASS COUNTY LAND CORNER RECORD

T. 139 R. 27 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
E14 R3 Corner common to sections 23, 24



EXISTING SURVEYS

**Original Government Survey**  
 Year surveyed 1863  
 Original monument Post

**Bearing Trees**  
 Species TAM  
 Diameter 7"  
 Bearing S70W  
 Distance 10 LKS

**Original Evidence Found**  
 Year of search \_\_\_\_\_ By \_\_\_\_\_  
 Monument found \_\_\_\_\_

**Original Bearing Trees Found**  
 Species \_\_\_\_\_  
 Diameter \_\_\_\_\_  
 Bearing \_\_\_\_\_  
 Distance \_\_\_\_\_

**Subsequent Corner Restoration**  
 Year surveyed 1913 By HARRY TODD  
 Location filed COUNTY SURVEY RECORD BOOK "A" P 576-580  
 Monument Set 2x2x7/8" STAKE PROPORTIONALLY  
1922 - GREENE, BOOK "O" P 175 FIND CORNER'S TIES  
1913 CURO BK 173 PG 53-75 MIF ROLL 12

**Evidence of Subsequent Corner Restoration**  
 Year of search 1936 By CCC  
Washburn Lake - BK # 7 P 3  
Temp Cor 40 CH. S of NE 23 - End 1/4 cor  
73 1/2 LKS N & 12.5 LKS W, 4" stake

**Bearing Trees, Reference Objects**  
 Species TAM TAM  
 Diameter 5" 8"  
 Bearing S40E N87W  
 Distance 44.50' 43.50'  
1913 TIES

**Bearing Trees, Reference Objects**  
Dead TAM TAM ref. Stake  
5.8" 6.6" on road  
S81E S72W 3.21 CH W. of  
53 LKS 46 LKS corner

**Subsequent Corner Restoration**  
 Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
 Location filed \_\_\_\_\_  
 Monument \_\_\_\_\_

**Evidence of Subsequent Corner Restoration Found**  
 Year of search \_\_\_\_\_ By \_\_\_\_\_

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
 Filed at \_\_\_\_\_ Date \_\_\_\_\_