


Index No. V 9

CASS COUNTY LAND CORNER RECORD

T. 139 R. 27 M. 5th Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
NE 32 Corner common to sections 28, 29, 32, 33



EXISTING SURVEYS

Original Government Survey

Year surveyed 1864  
Original monument Post

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Species	Bearing Trees			
	W. BIRCH	W. PINE	W. BIRCH	W. PINE
Diameter	<u>6"</u>	<u>24"</u>	<u>8"</u>	<u>30"</u>
Bearing	<u>N40E</u>	<u>N70W</u>	<u>S53E</u>	<u>S38W</u>
Distance	<u>22LKS</u>	<u>18LKS</u>	<u>25LKS</u>	<u>42LKS</u>

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1937 By CCC  
Location filed Lake Washburn BKT#1 P26  
Monument End Coy 75.87 CH. from S.

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Re monumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
Filed at \_\_\_\_\_ Date \_\_\_\_\_