


Index No. 27

CASS COUNTY LAND CORNER RECORD

T. 139 R. 27 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
S14 32 Corner common to sections 32



EXISTING SURVEYS

Original Government Survey

Year surveyed 1863  
Original monument Post

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees

Species ASPEN BL. OAK  
Diameter 12" 12"  
Bearing N20W S22W  
Distance 20 LKS. 19 LKS.

Original Bearing Trees Found

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed 1937 By CCC  
Location filed Washburn Lake - BK#2 P.5  
Monument Set approx 1/4 cor. 40 ch from west  
1939 - BK#10 P.19 - at 2640' from E - set approx  
corner

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_

Bearing Trees, Reference Objects

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Bearing Trees, Reference Objects

\_\_\_\_\_

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
Filed at \_\_\_\_\_ Date \_\_\_\_\_