


Index No. A 21

CASS COUNTY LAND CORNER RECORD

T. 139 R. 28 M. 5TH Coordinates: X NE 2 Y 1, 2 AND 35, 36-140-28  
Corner common to sections



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1863

Original monument POST

| Species         | Bearing        | Trees          | Distance        |
|-----------------|----------------|----------------|-----------------|
| <u>W. BIRCH</u> | <u>J. PINE</u> | <u>J. PINE</u> | <u>W. BIRCH</u> |
| <u>6"</u>       | <u>10"</u>     | <u>12"</u>     | <u>7"</u>       |
| <u>N84E</u>     | <u>S78E</u>    | <u>S74W</u>    | <u>N18W</u>     |
| <u>30 LKS</u>   | <u>35 LKS</u>  | <u>41 LKS</u>  | <u>6 LKS</u>    |

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Monument found \_\_\_\_\_

Original Bearing Trees Found

Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed 1920 By BEN CLARK

Location filed COUNTY RESURVEY 'E-B'

Monument IRON MONUMENT

1919, BEN CLARK, COUNTY BOOK "C" P. 316 FND 1/2 X 2 7/8" I.P.

SET 3 X 30" I.P.

Evidence of Subsequent Corner Restoration

Year of search 1939 By CCC

Washburn Lake - BK# 12 P. 1

Sket N. from center of road

1938 - BK# 13 P. 2 at 4950' from East - End city

cor: B.T.S: 25" w. pine stump N38E 35', 25" w. pine

S56 1/2 E 87', 25" w. pine S14 1/2 W 40.5', 20" w. pine stump

N72 1/2 W 63.8'

Bearing Trees, Reference Objects

| Species        | Bearing        | Distance       |
|----------------|----------------|----------------|
| <u>W. PINE</u> | <u>W. PINE</u> | <u>W. PINE</u> |
| <u>14"</u>     | <u>20"</u>     | <u>23"</u>     |
| <u>N87W</u>    | <u>N91E</u>    | <u>S87-30E</u> |
| <u>41.9'</u>   | <u>50.3'</u>   | <u>106.2'</u>  |

Bearing Trees, Reference Objects

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

Subsequent Corner Restoration

Year surveyed 2000 By CCSO

Location filed CCSO

Monument Found 2" O.D. Iron pipe, drove down 0.3' below road surface.

P. Pole, N1°W, 44.60' \* tag

13" P. Oak, S36°E, 52.39' \* (found)

24" W. Pine (dead), S22°W, 41.11' \* (found)

10" Spruce, S62°W, 87.26' \*

\* distance to double headed nail

Evidence of Subsequent Corner Restoration Found

Year of search May 1914 By \_\_\_\_\_

Imp rd order shows no survey

Remonumentation certificate prepared \_\_\_\_\_

Filed at \_\_\_\_\_

By \_\_\_\_\_

Date \_\_\_\_\_