


Index No. E 17

CASS COUNTY LAND CORNER RECORD

T. 139 R. 28 M. 57H Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
NE 10 Corner common to sections 2, 3, 10, 11



O = Corner

EXISTING SURVEYS

Original Government Survey  
Year surveyed 1864  
Original monument POST

Original Evidence Found  
Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

		Bearing Trees			
Species	<u>CHERRY</u>	<u>SPRUCE</u>	<u>LEDAR</u>	<u>SPRUCE</u>	
Diameter	<u>5"</u>	<u>7"</u>	<u>8"</u>	<u>9"</u>	
Bearing	<u>N70E</u>	<u>N22W</u>	<u>S55E</u>	<u>S53W</u>	
Distance	<u>20 LKS.</u>	<u>7 LKS</u>	<u>4 LKS</u>	<u>36 LKS</u>	

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration  
 Year surveyed 1920 By BEN CLARK  
 Location filed COUNTY RESURVEY 'E-8', 'E-9'  
 Monument IRON MONUMENT  
1919, BEN CLARK, COUNTY BOOK "C" P. 318 FIVE GOOD BITS  
(LEDAR DOWN) S52E 1.4', SPRUCE STUMP S51E 238'  
SET HUB SET I.P.

Evidence of Subsequent Corner Restoration Found  
 Year of search 1938 By CCC  
Washburn Lake - BK # 12 P. 4  
at 5019' from east orig cor 21'S End  
NE & NW BITS  
BK 12 P. 6 at 5398' from west End corner  
159' north

Bearing Trees, Reference Objects

Species	<u>BALSAM</u>	<u>BALSAM</u>	_____	_____
Diameter	<u>8"</u>	<u>9"</u>	_____	_____
Bearing	<u>N 89 W</u>	<u>S 16 E</u>	_____	_____
Distance	<u>13.2'</u>	<u>7'</u>	_____	_____

Bearing Trees, Reference Objects  
FEB 2003 JERRY L - LAND SEPT - IN  
POND - READING UNDER ICE

Subsequent Corner Restoration  
 Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
 Location filed \_\_\_\_\_  
 Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found  
 Year of search \_\_\_\_\_ By \_\_\_\_\_

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
 Filed at \_\_\_\_\_ Date \_\_\_\_\_