


Index No. E 19

CASS COUNTY LAND CORNER RECORD

T. 139 R. 28 M. 5TH Coordinates: X _____ Y _____
N 1/4 11 Corner common to sections 2, 11



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1864
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

		Bearing Trees	
Species	<u>Aspen</u>	<u>Aspen</u>	_____
Diameter	<u>8"</u>	<u>7"</u>	_____
Bearing	<u>N 75 E</u>	<u>S 20 W</u>	_____
Distance	<u>5 LKS</u>	<u>18 LKS</u>	_____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1920 By BEN CLARK
Location filed COUNTY RESURVEY "E-8"
Monument IRON MONUMENT
1919, BEN CLARK, COUNTY BOOK "C" P. 321 SET 2 1/2 x 4 8" I.P.

Evidence of Subsequent Corner Restoration

Year of search 1938 By CCC
Washburn Lake - BK # 12 P. 3
at 2640' from East - Set approx cor 3" Ash
may 1914, Twp rd order shows no survey

Bearing Trees, Reference Objects

Species	<u>POPLAR</u>	_____	_____
Diameter	<u>7"</u>	_____	_____
Bearing	<u>S 47 W</u>	_____	_____
Distance	<u>18.2'</u>	_____	_____

Bearing Trees, Reference Objects

_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____