


Index No. E 23

CASS COUNTY LAND CORNER RECORD

T. 139 R. 28 M. 5TH Coordinates: X _____ Y _____
N 1/4 12 Corner common to sections 1, 12



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1864
Original monument Post

Bearing Trees
Species Aspen Aspen
Diameter 8" 10"
Bearing NORTH S 10 E
Distance 6 LKS 58 LKS.

Original Evidence Found

Year of search _____ By _____
Monument found _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed 1920 By BEN CLARK
Location filed COUNTY RESURVEY "E-B"
Monument IRON MONUMENT
1919, BEN CLARK, COUNTY BOOK "C" P. 322 SET 2 1/2 x 48" I.P.

Evidence of Subsequent Corner Restoration

Year of search 1938 By CCC
Washburn Lake BK # 12 P. 1
at 2640' from east - Set approx cor 4" oak

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____
Filed at _____

By _____
Date _____