


Index No. E 7

CASS COUNTY LAND CORNER RECORD

T. 139 R. 28 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
N 1/4 8 Corner common to sections 5, 8



O = Corner

EXISTING SURVEYS

**Original Government Survey**

Year surveyed 1864

Original monument POST

Species	Bearing	Trees
<u>Aspen</u>	<u>BIECH</u>	
Diameter <u>9"</u>	<u>7"</u>	
Bearing <u>S 20 W</u>	<u>N 25 W</u>	
Distance <u>14 LKS</u>	<u>19 LKS</u>	

**Original Evidence Found**

Year of search \_\_\_\_\_ By \_\_\_\_\_

Monument found \_\_\_\_\_

**Original Bearing Trees Found**

Species	Diameter	Bearing	Distance

**Subsequent Corner Restoration**

Year surveyed 1922 By BEN CLARK

Location filed COUNTY RESURVEY 'E-9'

Monument IRON MONUMENT  
1919, BEN CLARK, COUNTY BOOK 'C' P. 331, FWD Corner  
P. 333, SET 2x40" I.P.

**Evidence of Subsequent Corner Restoration**

Year of search 1938 By CCC

Washburn Lake - BK # 12 P. 10  
at 2640' from E - Continue W from Approx loc.

**Bearing Trees, Reference Objects**

Species	Diameter	Bearing	Distance
<u>POPLAR</u>	<u>12"</u>	<u>S 20 E</u>	<u>17.5'</u>
<u>POPLAR</u>	<u>13"</u>	<u>S 35 W</u>	<u>19.6'</u>

**Bearing Trees, Reference Objects**

Species	Diameter	Bearing	Distance

**Subsequent Corner Restoration**

Year surveyed 5/02 By CCSO

Location filed \_\_\_\_\_

Monument N 1/4 - Found 2" OOPIP, up 0.1'  
On E of old grade.

8" W. Oak N 40° E 37.35' to dbl hd nail  
8" W. Oak S 60° E 32.21' to dbl hd nail  
6" Maple S 36° W 18.19' to dbl hd nail

**Evidence of Subsequent Corner Restoration Found**

Year of search June 1918 By \_\_\_\_\_

Trwp rd order shows no survey.

Remonumentation certificate prepared \_\_\_\_\_  
Filed at \_\_\_\_\_

By \_\_\_\_\_  
Date \_\_\_\_\_