Index No. J 17

CASS COUNTY LAND CORNER RECORD

T. 139 R. 28 M. 5TH Coordinates: X _____ Y _____

NE 15 Corner common to sections 10, 11, 14, 15



EXISTING SURVEYS

Original Government Survey

Year surveyed 1864

Original monument POST

Bearing Trees

Species	ASPEN	TAM	W PINE	TAM.
Diameter	10"	6"	10"	9"
Bearing	N 58 E	N 9 W	570 E	540 W
Distance	69 LKS	58 LKS	75 LKS	24 LKS

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species				
Diameter				
Bearing				
Distance				

Subsequent Corner Restoration

Year surveyed 1920 By BEN CLARK

Location filed COUNTY RESURVEY 'E-8, E-9, E-10"

Monument IRON MONUMENT

1919, BEN CLARK, COUNTY BOOK "C" P319 FND 60-7 BTS:

PINE 10" S 68 E 38.2', TAM STUMP 9" S 38 W 15.8',

SET ELM HUB SET 3X30" I.P.

Bearing Trees, Reference Objects

Species	ELM			
Diameter	8"			
Bearing	N 6 E			
Distance	58.5'			

Evidence of Subsequent Corner Restoration

Year of search 1938 By CCC

Washburn Lake - BK #13 P. 16

at 525' from east - Fnd 2" I.P. 63' North

BK 13 P. 18 at 5307 from W. Fnd 2" I.P.

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____