


Index No. J21

CASS COUNTY LAND CORNER RECORD

T. 139 R. 28 M. 5TH Coordinates: X _____ Y _____
NE 14 Corner common to sections 11, 12, 13, 14



O = Corner

EXISTING SURVEYS

Original Government Survey
 Year surveyed 1864
 Original monument POST

Original Evidence Found
 Year of search _____ By _____
 Monument found _____

Species	Bearing	Trees
<u>W. BIRCH</u>	<u>ELM</u>	<u>BR. OAK</u>
<u>10"</u>	<u>12"</u>	<u>6"</u>
<u>N50E</u>	<u>N50W</u>	<u>S45E</u>
<u>54 LKS</u>	<u>8 LKS</u>	<u>37 LKS</u>

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration
 Year surveyed 1920 By BEN CLARK
 Location filed COUNTY RESURVEY "E-8, E-10"
 Monument IRON MONUMENT
1919 - BEN CLARK, COUNTY BOOK "C" P. 336 TWD SE, NW
& SW B.T.S. SET 3x30" I.P.

Evidence of Subsequent Corner Restoration
 Year of search 1938 By CCC
Washburn Lake BC #13 P 14 -
at 5063' from east - find 2" I.P. 40' S.

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
 Location filed _____
 Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____