


T. 139 R. 28 M. 5TH Coordinates: X _____ Y _____
NE 18 Corner common to sections 7, 8, 17, 18



EXISTING SURVEYS

Original Government Survey

Year surveyed 1864
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species	<u>TAM.</u>	<u>TAM.</u>	<u>TAM.</u>	<u>TAM.</u>
Diameter	<u>6"</u>	<u>4"</u>	<u>7"</u>	<u>5"</u>
Bearing	<u>N50E</u>	<u>N60W</u>	<u>S30E</u>	<u>S45W</u>
Distance	<u>10 LKS</u>	<u>12 LKS</u>	<u>16 LKS</u>	<u>20 LKS</u>

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

O = Corner

Subsequent Corner Restoration

Year surveyed 1922 By BEN CLARK
Location filed COUNTY RESURVEY "E-9, E-11"
Monument IRON MONUMENT
1919, BEN CLARK, COUNTY BOOK "C" P. 333 SET 2 1/2 X 3 1/2
1/4" w/ CAP

Evidence of Subsequent Corner Restoration

Year of search 1938 By CCC
Washburn Lake - BK# 13 P. 22
at 5422' from east end I.P. 2" w/ cap surbed
M.C. 268' North

Bearing Trees, Reference Objects

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Bearing Trees, Reference Objects

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search Dec. 1919 By _____
Trap rd order shows no survey