Index No. N 25

CASS COUNTY LAND CORNER RECORD

T. 139 R. 28 M. 5TH Coordinates: X _____ Y _____

NE 24 Corner common to sections 13, 24 AND 18, 19-139-27



EXISTING SURVEYS

Original Government Survey

Year surveyed 1863

Original monument POST

Original Evidence Found

Year of search _____ By _____

Monument found _____

Bearing Trees				
Species	BIRCH	BIRCH	Y. PINE	BL. OAK
Diameter	14"	4"	16"	10"
Bearing	N54E	S10E	S61W	N8W
Distance	22 LKS	6 LKS	5 LKS.	20 LKS

Original Bearing Trees Found

Species				
Diameter				
Bearing				
Distance				

Subsequent Corner Restoration

Year surveyed 1922 By BEN CLARK

Location filed COUNTY RESURVEY "E-10"

Monument IRON MONUMENT

1919, BEN CLARK, BOOK "C" P.307 SET 4X36" POPLAR POST

1919, BEN CLARK ✓ P.314 SET 3X30" I.P.

Evidence of Subsequent Corner Restoration

Year of search 1936 By CCC

Washburn Lake - BK #7 P.24

at 79.67 CH from N. Fnd 2½" I.P marked 13/18 24/19

old SQ post S14E 77½ LKS

1938 - BK#12 P.13 - Start west from corner

BK#20 corner is 2300' ft N. of road

Bearing Trees, Reference Objects

Species	W. BIRCH			
Diameter	10"			
Bearing	N22-30E			
Distance	26.5'			

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____