


Index No. R 15

CASS COUNTY LAND CORNER RECORD

T. 139 R. 89 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
N14 27 Corner common to sections 22, 27



EXISTING SURVEYS

Original Government Survey

Year surveyed 1864  
Original monument POST

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees

Species W. BIRCH Y. PINE  
Diameter 7" 9"  
Bearing S 70 W N 15 E  
Distance 10 LKS 39 LKS.

Original Bearing Trees Found

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed 1922 By BEN CLARK  
Location filed COUNTY RESURVEY "E-10, E-12"  
Monument IRON MONUMENT  
1919, BEN CLARK, COUNTY BOOK "E" P. 308 SET 3x36" IRON POST  
✓ ✓ ✓ P. 316 I.P. 2x48"

Evidence of Subsequent Corner Restoration

Year of search 1939 By CCC  
Washington Lake - BK# 13 P. 28  
at 2640' from E - set approx 1/4 cor

Bearing Trees, Reference Objects

Species W. PINE STUMP  
Diameter 24"  
Bearing N 47 E  
Distance 46.5'

Bearing Trees, Reference Objects

\_\_\_\_\_

P-15

Subsequent Corner Restoration

Year surveyed 3/03 By CCSO  
Location filed #2003.013  
Monument 2" OD IP down 1.5', on E  
Co. Rd #60, old fence North, GPS  
and witness:

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

8" W. Pine N 48° W 57.65' \*  
1" Red Post S 60° E 74.00' \*  
P. Pole S 64° W 69.77' \*  
\* distance to double head nail

Remonumentation certificate prepared \_\_\_\_\_

By \_\_\_\_\_

Filed at \_\_\_\_\_

Date \_\_\_\_\_