



T. 139 R. 28 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
NE 25 Corner common to sections R4, 25 and 19, 30 - 139-27

EXISTING SURVEYS

**Original Government Survey**  
 Year surveyed 1863  
 Original monument POST

Species	Bearing	Trees
<u>ASPEN</u>	<u>ASPEN</u>	
<u>6"</u>	<u>8"</u>	
<u>N65<sup>1</sup>/<sub>2</sub>E</u>	<u>S 86 E</u>	
<u>631 LKS</u>	<u>611 LKS</u>	

**Original Evidence Found**  
 Year of search \_\_\_\_\_ By \_\_\_\_\_  
 Monument found \_\_\_\_\_

**Original Bearing Trees Found**

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

○ = Corner

**Subsequent Corner Restoration**  
 Year surveyed 1908 By JOHN CURO  
 Location filed COUNTY SURVEY RECORD BOOK A P364-368  
 Monument FIND ALL 4 OLD GANT BITS. SET TALL 4X4 TAM. POST.  
1922 - BEN CLARK - COUNTY RESURVEY - E-10 E-11  
1919 BEN CLARK, BOOK C P 307 SET 4x48" PINE POST  
 Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
<u>W. PINE</u>	<u>19"</u>	<u>N53-30E</u>	<u>366.6'</u>
<u>W. PINE</u>	<u>12"</u>	<u>S53-13E</u>	<u>366.5'</u>
<u>W. PINE</u>	<u>16"</u>	<u>S9-30W</u>	<u>326'</u>

**Evidence of Subsequent Corner Restoration**  
 Year of search 1937 By C.C.C. - Lake Washburn  
Find iron pipe in wild hay meadow pipe has cap:  
BK # 1 P. 5 24119  
70.08 CH. from east 25130  
77.23 CH. from S.  
BK # 20 corner 807 east of Gantol post on old grade  
 Bearing Trees, Reference Objects

(R-25)

**Subsequent Corner Restoration**  
 Year surveyed Mar 1998 By C.C. Land Dept. A.R.  
 Location filed \_\_\_\_\_  
 Monument Exc. condition

3/04 CCSO file #2003.013 found  
2" OD IP w/plumber cap, down 0.8  
in open Marsh, 832'± E. of old  
grade, no tree near. GPS.

**Evidence of Subsequent Corner Restoration Found**  
 Year of search \_\_\_\_\_ By \_\_\_\_\_