


Index No. T 9

CASS COUNTY LAND CORNER RECORD

T. 139 R. 20 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
E11429 Corner common to sections 28, 29



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1864  
Original monument POST

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees	
Species <u>SOFT MAPLE</u>	<u>SOFT MAPLE</u>
Diameter <u>7"</u>	<u>8"</u>
Bearing <u>NR3E</u>	<u>S 80W</u>
Distance <u>17 LKS</u>	<u>13 1/2 LKS.</u>

Original Bearing Trees Found	
Species _____	_____
Diameter _____	_____
Bearing _____	_____
Distance _____	_____

Subsequent Corner Restoration

Year surveyed 1922 By BEN CLARK  
Location filed COUNTY RESURVEY 'E-12'  
Monument IRON MONUMENT  
1918, BEN CLARK COUNTY BOOK 'C' P. 305 SET 3X3  
POPLAR POST P. 337 SET 2 1/2 x 48" I.P.

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Bearing Trees, Reference Objects

Species <u>POPLAR</u>	<u>PINE STUMP</u>
Diameter <u>8"</u>	<u>20"</u>
Bearing <u>S35E</u>	<u>N60W</u>
Distance <u>19.6'</u>	<u>52.2'</u>

Bearing Trees, Reference Objects

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Remonumentation certificate prepared \_\_\_\_\_

By \_\_\_\_\_

Filed at \_\_\_\_\_

Date \_\_\_\_\_