


Index No. V 7

CASS COUNTY LAND CORNER RECORD

T. 139 R. 28 M. 5th Coordinates: X _____ Y _____
N 1/4 32 Corner common to sections 29, 32



EXISTING SURVEYS

Original Government Survey

Year surveyed 1864
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

| Bearing Trees | |
|------------------------|---------------|
| Species <u>ASPEN</u> | <u>ASPEN</u> |
| Diameter <u>15"</u> | <u>12"</u> |
| Bearing <u>N50E</u> | <u>S71E</u> |
| Distance <u>21 LKS</u> | <u>11 LKS</u> |

| Original Bearing Trees Found | | | |
|------------------------------|-------|-------|-------|
| Species | _____ | _____ | _____ |
| Diameter | _____ | _____ | _____ |
| Bearing | _____ | _____ | _____ |
| Distance | _____ | _____ | _____ |

○ = Corner

Subsequent Corner Restoration

Year surveyed 1922 By BEN CLARK
Location filed COUNTY RESURVEY "E-12, E-14"
Monument IRON MONUMENT
1918, Ben Clark, County Book "C" P. 304 Fnd Corner
1919 ✓ ✓ P. 336 Fnd 5x36" N. Pine
Post. 2 8TS; 8" J. Pine (67W 37.6'); 6" Poplar N24W 209' Set
2x48" 11P.

Bearing Trees, Reference Objects

| | | | |
|----------|-------|-------|-------|
| Species | _____ | _____ | _____ |
| Diameter | _____ | _____ | _____ |
| Bearing | _____ | _____ | _____ |
| Distance | _____ | _____ | _____ |

Evidence of Subsequent Corner Restoration

Year of search 1939 By CC
Washburn Lake - BK # 12 P. 33
at 2640' from W1 - Set approx Cor.

Bearing Trees, Reference Objects

| | | | |
|----------|-------|-------|-------|
| Species | _____ | _____ | _____ |
| Diameter | _____ | _____ | _____ |
| Bearing | _____ | _____ | _____ |
| Distance | _____ | _____ | _____ |

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____
Filed at _____

By _____
Date _____