


Index No. 213

CASS COUNTY LAND CORNER RECORD

T. 139 R. 28 M. 5TH Coordinates: X _____ Y _____

SE 33 Corner common to sections 33,34



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1863
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

	Bearing	Trees	
Species	<u>Aspen</u>	<u>Aspen</u>	<u>Aspen</u>
Diameter	<u>12"</u>	<u>10"</u>	<u>11"</u>
Bearing	<u>N33E</u>	<u>S72E</u>	<u>S13W</u>
Distance	<u>53 LKS</u>	<u>11 LKS</u>	<u>8 LKS</u>

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1922 By BEN CLARK
Location filed COUNTY RESERVE 'E-12"
Monument IRON MONUMENT
1918, BEN CLARK BOOK "C" P. 296 SET 5x36" POPLAR POST.
1919 ✓ P 338 END 1918 BIT AND
BELOW POST SET 3x30" I.P.

Evidence of Subsequent Corner Restoration

Year of search 1939 By CCC
Washburn Lake - BK#13 P.44
at 5321' from west corner is 7' south
End 16" w. Pine S 30 E 46'

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
<u>N. PINE</u>	<u>10"</u>	<u>S 29 E</u>	<u>45.6'</u>
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____